
Fig.1



Best Available Copy

Fig.2




Fig.3




Fig.4




Fig.5




Fig.6




Fig.7






Fig.8



OBLON ET AL (703) 413-3000 DOCKET # 2622/8US SHEET 8 OF 12

8/12

Fig.9



Arrangement of Film Forming Chambers on Rotation Support Body

Fig.10





Fig.11



Slanting line portion: Actual Discharge Area

Fig.12




Fig.13





Fig.14



This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

☐ BLACK BORDERS
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
☐ FADED TEXT OR DRAWING
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
☐ SKEWED/SLANTED IMAGES
☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
☐ GRAY SCALE DOCUMENTS
☐ LINES OR MARKS ON ORIGINAL DOCUMENT
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
☐ OTHER:

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.